Bill To: aaa aaa aaaa aaa a a a a a

Ship To: aaa aa aa aa a aa a a a a a a

Tax Invoice No. 2736

Customer ABN: 12345678 E: aaaa@bbb.ccc.dd 28/10/2021

asghfashg sdkljadlkasj Pty Ltd

E: nbdmnabn@dsadndlls.com.au, M: 12345674, F: (02) 79877777

PO Box 1234 (203 vvvv n nnnnn, dk;slksa;ldkas sadsalk;dk NSW 2151

ABN: 7i8217398237, ACN: 321876291

Purchase Order No.

4200184648

BMS Reactive work Claim for Aug-Oct
Total Labour excluding GST \$ 2,800.00
Total Material excluding GST \$ 1,500.00

Date (X2 indicates 2 Tech on site)	Work Order No.	Work Location & Description	Labour Excl GST	Material Excl GST	Total Excl GST
July 16 2021	26018169	July 16 (4 hours on site): Investigate the problem why fans are not running Sept 28 (7 houtrs on site): Replace Faulty Controller that controls EF3 & 4. Reprogrammed controller.	\$1,200.00	\$750.00	\$1,950.00
24/09/2021	26018300	BMS computer at Sydenham was not communicating. Reset and enabled network connection. Reinstalled software as the system was coming with errors	\$500.00		\$500.00
8/10/2021		Lev2 West Complaining AC not working. Checked FCU3 Cooling Heating. Calibrated sensors.	\$500.00		\$500.00
14/10/2021	26058530	Replace Faulty Controller (No. 3) in Domain plant room. Offiste reprogramming COntroller on 14- 10-21. Onsite rplace controller on 15-10-21	\$600.00	\$750.00	\$1,350.00

Bill To: Ship To: Tax Invoice No. 2736 aaa aaa aa aa aa aa aa aa

aaa a a a a a	a a a a a a a a a a a										
									\$0.00		
									ψ0.00		
Total Excluding GST			\$	2,800.00	\$	1,500.00	\$	4,300.00			
GST				\$	280.00	\$	150.00	\$	430.00		
Total Claim (This Claim) Including GST			\$	3,080.00	\$	1,650.00	\$	4,730.00			

Bill To: aaa aaa aaaa aaa a a a a a Ship To: aaa aa aa aa a aa a a a a a a a Tax Invoice No. 2736